Issue detail

Issue detail

Created on	Nov 3, 2026, 6:43 PM PST
Created by	**Anna Chen** (F26-CEE120A_220A)
Total items	1
Sorted by	ID (Ascending)
Filtered by	Created on (Oct 27, 2026 - Nov 3, 2026)


Contents

#1: Column Clash with Curtain Wall 3

Issue detail

#1: Column Clash with Curtain Wall

Status	**Open**
Type	CL Coordination > Clash
ID	#1
Description	174 total clashes: 9 clashes between Structural Columns, Concrete-Rectangular-Column [1251742] in Chen-Building-Structural.rvt - 3D - STRUCTURAL COORDINATION and Chen-Building-Module-6.rvt - 3D - ARCHITECTURE - COORDINATION 7 clashes between Structural Columns, Concrete-Rectangular-Column [1251743] in Chen-Building-Structural.rvt - 3D - STRUCTURAL COORDINATION and Chen-Building-Module-6.rvt - 3D - ARCHITECTURE - COORDINATION 8 clashes between Structural Columns, Concrete-Rectangular-Column [1251744] in Chen-Building-Structural.rvt - 3D - STRUCTURAL COORDINATION and Chen-Building-Module-6.rvt - 3D - ARCHITECTURE - COORDINATION 9 clashes between Structural Columns, Concrete-Rectangular-Column [1251745] in Chen-Building-Structural.rvt - 3D - STRUCTURAL COORDINATION and Chen-Building-Module-6.rvt - 3D - ARCHITECTURE - COORDINATION 6 clashes between Structural Columns, Concrete-Rectangular-Column [1251746] in Chen-Building-Structural.rvt - 3D - STRUCTURAL COORDINATION and Chen-Build...



Assigned to	—
Created by	Anna Chen (F26-CEE120A_220A)
Created on	Nov 3, 2026
Location	—
Location details	—
Due date	—
Start date	—
Placement	Chen-Building-Structural.rvt
Root cause	—