Issue detail

Issue detail

Created on	Nov 3, 2026, 9:38 PM PST
Created by	**Kate Meleski** (F26-CEE120A_220A)
Total items	2
Sorted by	ID (Ascending)
Filtered by	Created on (Oct 27, 2026 - Nov 3, 2026)


Contents

#1: 1000 clashes across 280 Clash Groups 3
#2: 851 clashes across 209 Clash Groups 5

Issue detail

#1: 1000 clashes across 280 Clash Groups

Status	**Open**
Type	CL Coordination > Clash
ID	#1
Description	1000 total clashes: 8 clashes between Assembled Stair [365753] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 8 clashes between Assembled Stair [369197] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 24 clashes between Basic Roof [356827] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 1 clash between Basic Wall [356861] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 1 clash between Basic Wall [356862] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 6 clashes between Basic Wall [356864] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 7 clashes between Bas...




Assigned to	—
Created by	Kate Meleski (F26-CEE120A_220A)
Created on	Nov 3, 2026
Location	—
Location details	—
Due date	—
Start date	—
Placement	**Meleski - Building_detached_week 6.rvt**
Root cause	—

Issue detail

#2: 851 clashes across 209 Clash Groups

Status	Open
Type	CL Coordination > Clash
ID	#2



Description	851 total clashes: 6 clashes between Compound Ceiling [519800] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 4 clashes between Compound Ceiling [519808] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 14 clashes between Compound Ceiling [519818] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 2 clashes between Compound Ceiling [519842] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 8 clashes between Compound Ceiling [519850] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Structural 2 clashes between Compound Ceiling [519858] in Meleski - Building_detached_week 6.rvt - 3D - Architectural and Meleski - Building_Structural.rvt - 3D - Stru...
Assigned to	—
Created by	Kate Meleski (F26-CEE120A_220A)
Created on	Nov 3, 2026
Location	—
Location details	—
Due date	—
Start date	—
Placement	**Meleski - Building_detached_week 6.rvt**
Root cause	—